

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Teison
Hardware model:	AC0032T2A01
Firmware	v4.3.6.rc_S35.10.31.3.871120000
Tester:	Bob Elders
Date:	10/12/2021

	Step	OCPP Profile	Action	Timestamp	Pass	Remarks
BASIC	1	Core	Boot charging station	2021-12-03 09:14:26	Y	
	2	Core	Change availability	2021-12-03 09:15:19	Y	
	3	Core	Get Configuration	2021-12-03 09:15:51	Y	
	4	Core	Change Configuration	2021-12-03 09:25:52	Y	
	5	Core	Heartbeat	2021-12-03 09:26:35	Y	
	6	Core	Charging Session - Local - Plugin first	2021-12-03 09:37:18	Y	
	7	Core	Charging Session - Local - Identification first - Connection Loss	2021-12-03 09:37:31	Y	
	8	Core	Charging session - Local - Identification first - Connection TimeOut	2021-12-03 09:37:33	N	Only plugin first supported
	9	Core	Hard Reset - During Charging session	2021-12-03 10:01:25	Y	
	10	Core	Hard Reset - No charging session	2021-11-03 10:16:39	Y	
	11	Core	Soft Reset - During Charging session	2021-11-03 10:23:52	Y	
	12	Core	Soft Reset - No charging session	2021-11-03 10:25:23	Y	
	13	Core	Charging session - Local - Unauthorized	2021-11-03 10:25:25	Y	
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2021-11-03 10:28:11	Y	
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2021-11-03 10:29:47	Y	
	16	Core	Hardware related notification / error condition	2021-11-03 10:30:20	Y	
	17	Firmware Management	Remote Firmware update - Download failed	2021-12-03 10:36:07	Y	
	18	Firmware Management	Remote Firmware update - Installation failed	2021-12-03 10:44:15	Y	
	19	Firmware Management	Remote Firmware update - Download & install	2021-12-10 10:38:30	Y	
	20	Firmware Management	Remote get diagnostics report	2021-11-03 11:00:17	Y	
	21	Firmware Management	Remote get diagnostics - fail	2021-12-10 11:46:05	Y	
	22	Core	Clear cache	2021-11-03 11:03:58	Y	
	23	Remote Trigger	TriggerMessage	2021-11-03 11:09:16	Y	