

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Sinexcel
Hardware model:	C6EUAC
Firmware	OCPP1.6_V000.001.024
Tester:	Bob Elders
Date:	15/04/2022

BASIC	Step	OCPP Profile	Action	Timestamp	Pass	Remarks
	1	Core	Boot charging station	2022-04-08	Y	
	2	Core	Change availability	2022-04-08	Y	
	3	Core	Get Configuration	2022-04-08	Y	
	4	Core	Change Configuration	2022-04-08	Y	
	5	Core	Heartbeat	2022-04-08	Y	
	6	Core	Charging Session - Local - Plugin first	2022-04-08	Y	
	7	Core	Charging Session - Local - Identification first - Connection Loss	2022-04-08	Y	
	8	Core	Charging session - Local - Identification first - Connection TimeOut	2022-04-08	N	Authentication first not supported
	9	Core	Hard Reset - During Charging session	2022-04-08	Y	
	10	Core	Hard Reset - No charging session	2022-04-08	Y	
	11	Core	Soft Reset - During Charging session	2022-04-08	Y	
	12	Core	Soft Reset - No charging session	2022-04-08	Y	
	13	Core	Charging session - Local - Unauthorized	2022-04-08	Y	
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2022-04-08	Y	
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2022-04-08	N	RemoteStartFirst not supported (similar to 8)
	16	Core	Hardware related notification / error condition	2022-04-08	Y	
	17	Firmware Management	Remote Firmware update - Download failed	2022-04-08	Y	
	18	Firmware Management	Remote Firmware update - Installation failed	2022-04-08	Y	DownloadFailed instead of InstallationFailed
	19	Firmware Management	Remote Firmware update - Download & install	2022-04-08	N	No FirmwareStatusNotification:Installed
	20	Firmware Management	Remote get diagnostics report	2022-04-15	Y	
	21	Firmware Management	Remote get diagnostics - fail	2022-04-15	Y	
	22	Core	Clear cache	2022-04-15	Y	
	23	Remote Trigger	TriggerMessage	2022-04-08	Y	