

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	StarCharge
Hardware model:	Aurora MID 11
Firmware	1.0.0.0.6b106_MID11
Tester:	Carmen Schaack
Date:	15/06/2022

BASIC	Step	OCPP Profile	Action	Timestamp	Pass	Remarks
	1	Core	Boot charging station	15/06/2022	Y	
	2	Core	Change availability	15/06/2022	Y	
	3	Core	Get Configuration	15/06/2022	Y	
	4	Core	Change Configuration	15/06/2022	Y	
	5	Core	Heartbeat	15/06/2022	Y	
	6	Core	Charging Session - Local - Plugin first	15/06/2022	Y	
	7	Core	Charging Session - Local - Identification first - Connection Loss	15/06/2022	Y	
	8	Core	Charging session - Local - Identification first - Connection TimeOut	15/06/2022	Y	
	9	Core	Hard Reset - During Charging session	15/06/2022	Y	
	10	Core	Hard Reset - No charging session	15/06/2022	Y	
	11	Core	Soft Reset - During Charging session	15/06/2022	Y	
	12	Core	Soft Reset - No charging session	15/06/2022	Y	
	13	Core	Charging session - Local - Unauthorized	15/06/2022	Y	
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	15/06/2022	Y	
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	15/06/2022	Y	
	16	Core	Hardware related notification / error condition	15/06/2022	Y	
	17	Firmware Management	Remote Firmware update - Download failed	15/06/2022	Y	
						It would be ideal to get an 'installation failed' message when a charge station attempts but fails to install FW.
	18	Firmware Management	Remote Firmware update - Installation failed	15/06/2022	N	
	19	Firmware Management	Remote Firmware update - Download & install	15/06/2022	Y	
	20	Firmware Management	Remote get diagnostics report	15/06/2022	Y	
	21	Firmware Management	Remote get diagnostics - fail	15/06/2022	Y	
	22	Core	Clear cache	15/06/2022	Y	
23	Remote Trigger	TriggerMessage	15/06/2022	Y		