

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Rolec
Hardware model:	Zura 22KW
Firmware	0.6.4
Tester:	Wei Wang
Date:	22-01-24

Step	OCPP Profile	Action	Timestamp	Pass	Remarks
1	Core	Boot charging station	2023-10-26	Y	* The charge station only supports secure websocket connection
2	Core	Change availability	2023-10-26	Y	
3	Core	Get Configuration	2023-10-26	Y	
4	Core	Change Configuration	2023-10-26	Y	
5	Core	Heartbeat	2023-10-26	Y	
6	Core	Charging Session - Local - Plugin first	2023-10-26	Y	
7	Core	Charging Session - Local - Identification first - Connection Loss	2024-01-22	Y	*Stop Transaction received as expected
8	Core	Charging session - Local - Identification first - Connection TimeOut	2023-10-26	Y	
9	Core	Hard Reset - During Charging session	2023-10-26	Y	* Stop Transaction received before the charger reboots as expected.
10	Core	Hard Reset - No charging session	2023-10-26	Y	
11	Core	Soft Reset - During Charging session	2023-10-26	Y	* Stop Transaction received before the charger reboots as expected.
12	Core	Soft Reset - No charging session	2023-10-26	Y	
13	Core	Charging session - Local - Unauthorized	2023-10-26	Y	
14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2023-10-26	Y	
15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2023-10-26	Y	
16	Core	Hardware related notification / error condition	2024-01-22	Y	
17	Firmware Management	Remote Firmware update - Download failed	2023-10-26	Y	* DownloadFailed received as expected.
18	Firmware Management	Remote Firmware update - Installation failed	2023-10-26	Y	* Received DownloadFailed instead of InstallationFailed.
19	Firmware Management	Remote Firmware update - Download & install	2024-01-22	Y	
20	Firmware Management	Remote get diagnostics report	2023-10-26	Y	
21	Firmware Management	Remote get diagnostics - fail	2024-01-22	Y	
22	Core	Clear cache	2023-10-26	Y	
23	Remote Trigger	TriggerMessage	2024-01-22	Y	