

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON

Manufacturer Name:	Bender
Hardware model:	CC613
Firmware	5.12.1-10916
Tester:	Carmen Schaack & Bob Elders
Date:	26/10/2021

BASIC

Step	OCPP Profile	Action	Timestamp	Pass	Remarks
1	Core	Boot charging station	2021-10-26	Y	
2	Core	Change availability	2021-10-26	Y	
3	Core	Get Configuration	2021-10-26	Y	
4	Core	Change Configuration	2021-10-26	Y	
5	Core	Heartbeat	2021-10-26	Y	
6	Core	Charging Session - Local - Plugin first	2021-10-26	Y	
7	Core	Charging Session - Local - Identification first - Connection Loss	2021-10-26	Y	
8	Core	Charging session - Local - Identification first - Connection TimeOut	2021-10-26	Y	
9	Core	Hard Reset - During Charging session	2021-10-26	Y	Session continues after reboot
10	Core	Hard Reset - No charging session	2021-10-26	Y	
11	Core	Soft Reset - During Charging session	2021-10-26	Y	Only active connector reboots, session stops, no BootNotification
12	Core	Soft Reset - No charging session	2021-10-26	Y	
13	Core	Charging session - Local - Unauthorized	2021-10-26	Y	
14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2021-10-26	Y	
15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2021-10-26	Y	
16	Core	Hardware related notification / error condition	2021-10-26	Y	
17	Firmware Management	Remote Firmware update - Download failed	2021-10-26	Y	
18	Firmware Management	Remote Firmware update - Installation failed	2021-10-26	Y	
19	Firmware Management	Remote Firmware update - Download & install	2021-10-26	Y	
20	Firmware Management	Remote get diagnostics report	2021-10-26	Y	
21	Firmware Management	Remote get diagnostics - fail	2021-10-26	Y	
22	Core	Clear cache	2021-10-26	Y	
23	Remote Trigger	TriggerMessage	2021-10-26	Y	Trigger on MeterValues contains MeterValuesAlignedData