

Test Script for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Tritium
Hardware model:	TRI153-RTM-01
Firmware	csb.21.1.3
Tester:	Bob Elders
Date:	09/07/2021

	Step	OCPP Profile	Action	Timestamp	Pass	Remarks
BASIC	1	Core	Boot charging station	2021-07-09 13:51:14	Y	
	2	Core	Change availability	2021-07-09 13:51:28	Y	
	3	Core	Get Configuration	2021-07-09 13:52:44	Y	
	4	Core	Change Configuration	2021-07-09 13:55:21	Y	
	5	Core	Heartbeat	2021-07-09 13:55:24	Y	
	6	Core	Charging Session - Local - Plugin first	2021-07-09 14:12:16	Y	Current.Offered: 0 in MeterValues
	7	Core	Charging Session - Local - Identification first - Connection Loss	2021-07-09 14:17:35	Y	
	8	Core	Charging session - Local - Identification first - Connection TimeOut	2021-07-09 14:29:57	Y	
	9	Core	Hard Reset - During Charging session	2021-07-09 14:30:10	Y	
	10	Core	Hard Reset - No charging session	2021-07-09 14:32:46	Y	
	11	Core	Soft Reset - During Charging session	2021-07-09 14:41:24	Y	
	12	Core	Soft Reset - No charging session	2021-07-09 14:41:49	Y	
	13	Core	Charging session - Local - Unauthorized	2021-07-09 14:46:29	Y	
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2021-07-09 14:51:23	Y	
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2021-07-09 14:53:59	Y	
	16	Core	Hardware related notification / error condition	2021-07-09 14:58:36	Y	
	17	Firmware Management	Remote Firmware update - Download failed	2021-07-09 15:01:20	Y	
	18	Firmware Management	Remote Firmware update - Installation failed	2021-07-09 15:05:04	Y	
	19	Firmware Management	Remote Firmware update - Download & install	09/07/2021 15:48	Y	
	20	Firmware Management	Remote get diagnostics report	2021-07-09 15:12:06	Y	No status: uploading received
	21	Firmware Management	Remote get diagnostics - fail	2021-07-09 15:15:12	N	Status:uploaded received after invalid URL
	22	Core	Clear cache	2021-07-09 15:17:16	Y	
	23	Remote Trigger	TriggerMessage	2021-07-09 15:18:35	Y	