

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	SDEE
Hardware model:	ADC432040T2JC2D36
Firmware	v4.6.0-td4_S35.00.31.3.cf11200104
Tester:	Carmen Schaack
Date:	05/07/2022

	Step	OCPP Profile	Action	Timestamp	Pass	Remarks
BASIC	1	Core	Boot charging station	2022-07-05 :Y		
	2	Core	Change availability	2022-07-05 :Y		
	3	Core	Get Configuration	2022-07-05 :Y		
	4	Core	Change Configuration	2022-07-05 :Y		Current.Offered currently not supported but will be changed before smart charging test.
	5	Core	Heartbeat	2022-07-05 :Y		
	6	Core	Charging Session - Local - Plugin first	2022-07-05 :Y		
	7	Core	Charging Session - Local - Identification first - Connection Loss	2022-07-05 :Y		
	8	Core	Charging session - Local - Identification first - Connection TimeOut	2022-07-05 :Y		
	9	Core	Hard Reset - During Charging session	2022-07-05 :Y		Hard and soft reset behave the same.
	10	Core	Hard Reset - No charging session	2022-07-05 :Y		
	11	Core	Soft Reset - During Charging session	2022-07-05 :Y		
	12	Core	Soft Reset - No charging session	2022-07-05 :Y		
	13	Core	Charging session - Local - Unauthorized	2022-07-05 :Y		No authorize.req on remoteStartTransaction because AuthorizeRemoteTxReq uests set to false.
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2022-07-05 :Y		
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2022-07-05 :Y		
	16	Core	Hardware related notification / error condition	2022-07-05 :Y		
	17	Firmware Management	Remote Firmware update - Download failed	2022-07-05 :Y		
	18	Firmware Management	Remote Firmware update - Installation failed	2022-07-05 :Y		
	19	Firmware Management	Remote Firmware update - Download & install	2022-07-05 :Y		
	20	Firmware Management	Remote get diagnostics report	2022-07-05 :Y		
	21	Firmware Management	Remote get diagnostics - fail	2022-07-05 :Y		
	22	Core	Clear cache	2022-07-05 :Y		
	23	Remote Trigger	TriggerMessage	2022-07-05 :Y		