

Test Script for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Etrell
Hardware model:	INCH PRO/DUO
Firmware	5.2
Tester:	Bob Elders, Retest done by Mohanad Elsayy
Date:	16/03/2023 (Retest Date)

BASIC	Step	OCPP Profile	Action	Pass	Remarks
	1	Core	Boot charging station	Y	StatusNotification with errorCode: OtherError
	2	Core	Change availability	Y	
	3	Core	Get Configuration	Y	
	4	Core	Change Configuration	Y	Retest: Change of websocketpinginterval configuration successful
	5	Core	Heartbeat	Y	Heartbeat received successfully during a retest.
	6	Core	Charging Session - Local - Plugin first	Y	
	7	Core	Charging Session - Local - Identification first - Connection Loss	Y	
	8	Core	Charging session - Local - Identification first - Connection TimeOut	Y	
	9	Core	Hard Reset - During Charging session	Y	
	10	Core	Hard Reset - No charging session	Y	
	11	Core	Soft Reset - During Charging session	Y	
	12	Core	Soft Reset - No charging session	Y	
	13	Core	Charging session - Local - Unauthorized	Y	
	14	Core	Charging session - Remote Start and Stop Transaction - Cable first	Y	
	15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	Y	
	16	Core	Hardware related notification / error condition	Y	
	17	Firmware Management	Remote Firmware update - Download failed	N	No FirmwareStatusNotification: DownloadFailed received
	18	Firmware Management	Remote Firmware update - Installation failed	Y	
	19	Firmware Management	Remote Firmware update - Download & install	Y	
	20	Firmware Management	Remote get diagnostics report	Y	
	21	Firmware Management	Remote get diagnostics - fail	Y	
	22	Core	Clear cache	Y	
	23	Remote Trigger	TriggerMessage	Y	