

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	Waybler
Hardware model:	Dynamic
Firmware	3.0.24
Tester:	Mohanad Elsayy
Date:	16/07/2024

Step	OCPP Profile	Action	Timestamp	Pass	Remarks
1	Core	Boot charging station	2024-05-30	Y	☒When connected via SIM, the ICCID and IMSI are not sent
2	Core	Change availability	2024-05-30	Y	
3	Core	Get Configuration	2024-05-30	Y	
4	Core	Change Configuration	2024-05-30	Y	
5	Core	Heartbeat	2024-05-30	Y	
6	Core	Charging Session - Local - Plugin first	2024-05-30	Y	
7	Core	Charging Session - Local - Identification first - Connection Loss	2024-05-30	Y	
8	Core	Charging session - Local - Identification first - Connection TimeOut	2024-05-30	Y	
9	Core	Hard Reset - During Charging session	2024-05-30	Y	☒Goes to "Preparing" instead of "Finishing" after the reboot is done
10	Core	Hard Reset - No charging session	2024-05-30	Y	
11	Core	Soft Reset - During Charging session	2024-05-30	Y	☒Does not actually reboot the charger ☒Goes to "Preparing" instead of "Finishing" after the reboot is done
12	Core	Soft Reset - No charging session	2024-05-30	Y	☒Does not actually reboot the charger
13	Core	Charging session - Local - Unauthorized	2024-05-30	Y	
14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2024-05-30	Y	
15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2024-05-30	Y	
16	Core	Hardware related notification / error condition	2024-05-30	N/A	- Could not simulate
17	Firmware Management	Remote Firmware update - Download failed		N/A	- Carried out by the manufacturer
18	Firmware Management	Remote Firmware update - Installation failed		N/A	
19	Firmware Management	Remote Firmware update - Download & install		N/A	
20	Firmware Management	Remote get diagnostics report	2024-05-30	Y	
21	Firmware Management	Remote get diagnostics - fail	2024-05-30	Y	
22	Core	Clear cache	2024-05-30	Y	
23	Remote Trigger	TriggerMessage	2024-05-30	Y	