

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON	
Manufacturer Name:	EFACEC
Hardware model:	QC120
Firmware	QC120_N_MSC64_1.6w_8.3.13_full
Tester:	Mohanad Elsayy
Date:	010/10/2023

Step	OCPP Profile	Action	Timestamp	Pass	Remarks
1	Core	Boot charging station	2023-06-01 10:18:3	Y	
2	Core	Change availability	2023-06-01 10:20:3	Y	
3	Core	Get Configuration	2023-06-01 10:20:4	Y	
4	Core	Change Configuration	2023-06-01 10:22:2	Y	
5	Core	Heartbeat	2023-06-01 10:22:2	Y	
6	Core	Charging Session - Local - Plugin first	2023-06-01 10:27:1	Y	
7	Core	Charging Session - Local - Identification first - Connection Loss	14/09/2023 10:47	Y	
8	Core	Charging session - Local - Identification first - Connection TimeOut	2023-06-01 10:48:4	Y	
9	Core	Hard Reset - During Charging session	2023-06-01 10:58:4	Y	
10	Core	Hard Reset - No charging session	2023-06-01 11:07:2	Y	
11	Core	Soft Reset - During Charging session	2023-06-01 11:15:2	Y	
12	Core	Soft Reset - No charging session	2023-06-01 11:21:3	Y	
13	Core	Charging session - Local - Unauthorized	2023-06-01 11:22:0	Y	
14	Core	Charging session - Remote Start and Stop Transaction - Cable first	2023-06-01 11:24:3	Y	
15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	2023-06-01 11:26:0	Y	
16	Core	Hardware related notification / error condition	2023-06-01 11:26:3	Y	
17	Firmware Management	Remote Firmware update - Download failed	2023-06-01 11:28:4	Y	
18	Firmware Management	Remote Firmware update - Installation failed	2023-06-01 11:32:4	Y	
19	Firmware Management	Remote Firmware update - Download & install	2023-06-01 11:49:3	Y	
20	Firmware Management	Remote get diagnostics report	2023-06-01 11:50:4	Y	
21	Firmware Management	Remote get diagnostics - fail	2023-06-01 11:51:2	Y	
22	Core	Clear cache	2023-06-01 11:51:4	Y	
23	Remote Trigger	TriggerMessage	2023-06-01 13:13:0	Y	