

Test Report for Charge Stations connected to GreenFlux Platform using OCPP1.6 via JSON

Manufacturer Name:	Efacec
Hardware model:	QC60
Firmware	QC60_N_MSC64_1.6w_8.3.18_1_full
Tester:	Mohanad Elsayy
Date:	20/03/2024

Step	OCPP Profile	Action	Timestamp	Pass	Remarks
1	Core	Boot charging station	2023-11-02	Y	
2	Core	Change availability	2023-11-02	Y	
3	Core	Get Configuration	2023-11-02	Y	
4	Core	Change Configuration	2023-11-02	Y	
5	Core	Heartbeat	2023-11-02	Y	
6	Core	Charging Session - Local - Plugin first	2023-11-02	Y	
7	Core	Charging Session - Local - Identification first - Connection Loss	2023-11-02	Y	
8	Core	Charging session - Local - Identification first - Connection TimeOut	2023-11-02	Y	
9	Core	Hard Reset - During Charging session	21/11/2023	Y	
10	Core	Hard Reset - No charging session	21/11/2023	Y	
11	Core	Soft Reset - During Charging session	21/11/2023	Y	
12	Core	Soft Reset - No charging session	21/11/2023	Y	
13	Core	Charging session - Local - Unauthorized	21/11/2023	Y	
14	Core	Charging session - Remote Start and Stop Transaction - Cable first	21/11/2023	Y	
15	Core	Charging session - Remote Start Transaction - Request first - Unlock Connector	21/11/2023	Y	
16	Core	Hardware related notification / error condition	21/11/2023	Y	
17	Firmware Management	Remote Firmware update - Download failed	20/03/2024	Y	
18	Firmware Management	Remote Firmware update - Installation failed	20/03/2024	Y	
19	Firmware Management	Remote Firmware update - Download & install	20/03/2024	Y	
20	Firmware Management	Remote get diagnostics report	21/11/2023	Y	
21	Firmware Management	Remote get diagnostics - fail	21/11/2023	Y	
22	Core	Clear cache	21/11/2023	Y	
23	Remote Trigger	TriggerMessage	21/11/2023	Y	